

Figure 2
Generalized Geologic Section Across the Balcones Fault Zone